## **ANNEX I**

## EVENT AND ACTION PLAN FOR MARINE WATER QUALITY MONITORING

 www.erm.com
 Version: 0
 Project No.: 0505354
 Client: CAPCO, HK Electric, HKLTL
 13 October 2021

 P:\Projects\0505354 CLP Power Hong Kong Limited FSRU Pre-con
 EM&A.RC\02 Deliverables\28 Monthly EM&A Report\2021-09\Rev 0\0505354\_Monthly EM&A

 Report\_2021-09\_Rev\_0.docx
 FRU

## TABLE I.1 EVENT AND ACTION PLAN FOR MARINE WATER QUALITY MONITORING

Event	Action				
	ET	IEC	Contractor(s)	<b>Project Proponents</b>	
Action Level being exceeded by one sampling day	<ol> <li>Repeat <i>in-situ</i> measurement to confirm findings;</li> <li>Check monitoring data, plant, equipment and Contractor(s)'s working methods;</li> <li>Identify source(s) of impact and record in notification of exceedance;</li> <li>Inform IEC, Contractor(s) and Project Proponents.</li> </ol>	<ol> <li>Check monitoring data submitted by ET and Contractor(s)'s working methods.</li> </ol>	<ol> <li>Confirm receipt of notification of exceedance in writing;</li> <li>Check plant and equipment and rectify unacceptable practice.</li> </ol>	<ol> <li>Confirm receipt of notification of exceedance in writing.</li> </ol>	
Action Level being exceeded by two or more consecutive sampling days	<ol> <li>Repeat <i>in-situ</i> measurement to confirm findings;</li> <li>Check monitoring data, plant, equipment and Contractor(s)'s working methods;</li> <li>Identify source(s) of impact and record in notification of exceedance;</li> <li>Inform IEC, Contractor(s) and Project Proponents;</li> <li>Discuss with IEC and Contractor(s) on additional mitigation measures and ensure that they are implemented.</li> </ol>	<ol> <li>Check monitoring data submitted by ET and Contractor(s)'s working methods;</li> <li>Discuss with ET and Contractor(s) on additional mitigation measures and advise Project Proponents accordingly;</li> <li>Assess the effectiveness of the implemented mitigation measures.</li> </ol>	<ol> <li>Confirm receipt of notification of exceedance in writing;</li> <li>Check plant and equipment and rectify unacceptable practice;</li> <li>Consider changes of working methods;</li> <li>Discuss with ET and IEC on additional mitigation measures and propose them to Project Proponents within 3 working days;</li> <li>Implement the agreed mitigation measures.</li> </ol>	exceedance in writing;	

Event	Action				
Event	ET	IEC	Contractor(s)	<b>Project Proponents</b>	
Limit Level being exceeded by one sampling day	<ul> <li>confirm findings;</li> <li>2. Check monitoring data, plant, equipment and Contractor(s)'s working methods;</li> <li>3. Identify source(s) of impact and record in notification of exceedance;</li> <li>4. Inform IEC, Contractor(s), Project Proponents and EPD;</li> </ul>	<ol> <li>Check monitoring data submitted by ET and Contractor(s)'s working methods;</li> <li>Discuss with ET and Contractor(s) on additional mitigation measures and advise Project Proponents accordingly;</li> <li>Assess the effectiveness of the implemented mitigation measures.</li> </ol>	<ol> <li>Confirm receipt of notification of exceedance in writing;</li> <li>Check plant and equipment and rectify unacceptable practice;</li> <li>Critically review the need to change working methods;</li> <li>Discuss with ET and IEC on additional mitigation measures and propose them to Project Proponents within 3 working days;</li> <li>Implement the agreed mitigation measures.</li> </ol>	<ol> <li>Confirm receipt of notification of exceedance in writing;</li> <li>Discuss with the IEC on the proposed additional mitigation measures and agree on the mitigation measures to be implemented;</li> <li>Ensure additional mitigation measures are properly implemented;</li> <li>Request Contractor(s) to critically review the working methods.</li> </ol>	
Limit Level being exceeded by two or more consecutive sampling days	<ul> <li>confirm findings;</li> <li>2. Check monitoring data, plant, equipment and Contractor(s)'s working methods;</li> <li>3. Identify source(s) of impact and record in notification of exceedance;</li> <li>4. Inform IEC, Contractor(s), Project Proponents and EPD;</li> </ul>	<ol> <li>Check monitoring data submitted by ET and Contractor(s)'s working methods;</li> <li>Discuss with ET and Contractor(s) on additional mitigation measures and advise Project Proponents accordingly;</li> <li>Assess the effectiveness of the implemented mitigation measures.</li> </ol>	<ol> <li>Confirm receipt of notification of exceedance in writing;</li> <li>Check plant and equipment and rectify unacceptable practice;</li> <li>Critically review the need to change working methods;</li> <li>Discuss with ET and IEC on additional mitigation measures and propose them to Project Proponents within 3 working days;</li> <li>Implement the agreed mitigation measures;</li> <li>As directed by Project Proponents, slow down or stop all or part of the marine construction works until no exceedance of Limit Level.</li> </ol>	<ol> <li>Confirm receipt of notification of exceedance in writing;</li> <li>Discuss with the IEC on the proposed additional mitigation measures and agree on the mitigation measures to be implemented;</li> <li>Ensure additional mitigation measures are properly implemented;</li> <li>Request Contractor(s) to critically review the working methods;</li> <li>Consider and instruct, if necessary, the Contractor(s) to slow down or to stop all or part of the marine construction works until no exceedance of Limit Level.</li> </ol>	