HONG KONG OFFSHORE LNG TERMINAL PROJECT Monthly Environmental Monitoring and Audit (EM&A) Report for July 2021	
ANNEX P	
ANNEX	
MARINE TRAVEL ROUTES OF WORKING VESSELS ENTERING N	MARINE PARK

Marine Park Record (July 2021)

<b>Construction Activities</b>	Vessel	Duration From	Duration To	Duration Minutes	Tracking
Nil (Note 1)	DE YUAN	7/5/2021 19:03	7/5/2021 19:33	30	TOT YUMN STOT OF THE STOT OF T
Nil (Note 1)	HYSY698	7/8/2021 7:59	7/8/2021 8:11	12	3)  MAY YANG SAH YOU 660 X 2012 YOU 600 Y 749 Speed 3 3 Indis
Nil (Note 1)	DE YUAN	7/13/2021 19:41	7/13/2021 19:47	6	Some op-nore o
Nil (Note 1)	DE YUAN	7/22/2021 15:46	7/22/2021 15:59	13	(B) VIVIAN (B)
Nil (Note 1)	DE YUAN	7/22/2021 16:47	7/22/2021 17:17	30	17/7/50 21-07-22 17-2519 8.5 knot led 0.5 kn

## Marine Park Record (July 2021)

		IVIAIIII	CI alk No	cord (July A	2021)
<b>Construction Activities</b>	Vessel	Duration From	Duration To	<b>Duration Minutes</b>	Tracking
Anchor Deployment	DE YUAN	7/24/2021 12:41	7/24/2021 16:11	210	DE YUMA DE 1147-24 16:29 50 Speed 0 6 knots
Nil (Note 2)	DE YUAN	7/24/2021 19:05	7/24/2021 22:55	230	DE WANN 201-07-35 02 54 52* Speed 0 5 knots.  1905551 1.3 knots
Nil (Note 1)	DE YUAN	7/25/2021 7:17	7/25/2021 9:47	149	To your management of the control of
Nil (Note 1)	DE YUAN	7/28/2021 19:29	7/28/2021 20:58	89	COT YMAN  COLOR OF THE STATE OF

Notes:

<sup>(1)</sup> Working vessels were utlised as guard boats to impede other vessels for protection of both anchors and vessels during the period due to safety concern.

(2) Working vessel was utilised to assist in the replacement of flashing lights for the yellow buoys deployed for indication of positions of anchors extending from the main construction vessel as per the requirement stipulated in the Marine Department Notice No. 180/2020.