HONG KONG OFFSHORE LNG TERMINAL PROJECT Monthly Environmental Monitoring and Audit (EM&A) Report for January 2023 **ANNEX E** WASTE MANAGEMENT CHECKLIST

Report_2023-01_Rev_0.docx

TABLE E.1 WASTE MANAGEMENT CHECKLIST

| Activities | Timing | Checking | Works Area(s) | Compliance (✓) / |
|---|----------------------------------|------------|---|--|
| | | Frequency | | Non-compliance (x) |
| Necessary waste disposal permits or licences have been obtained. | Before the commencement of works | Once | FEP-01/558/2018/A FEP-02/558/2018/A FEP-03/558/2018/B | ✓ ✓ ✓ |
| Dredged sediments are managed and disposed in accordance with PNAP ADV-21: Management | Throughout the dredging works | Each Month | FEP-02/558/2018/A | No marine sediment was dredged/ excavated in the reporting period. |
| Framework for Disposal of Dredged/ Excavated Sediment and Dumping at Sea Ordinance (DASO). | | | FEP-03/558/2018/B | No marine sediment was dredged/ excavated in the reporting period. |
| Waste are collected by | Throughout the | Each Week | FEP-01/558/2018/A | ✓ |
| licensed waste hauliers and disposed of at | works | | FEP-02/558/2018/A FEP-03/558/2018/B | ✓ ✓ |
| licensed sites. | | | FEF-03/330/2010/B | • |
| Records of quantities of | Throughout the | Each Month | FEP-01/558/2018/A | ✓ |
| wastes generated, | works | | FEP-02/558/2018/A | ✓ ✓ |
| recycled and disposed of and the disposal sites are properly kept. | | | FEP-03/558/2018/B | • |
| Sufficient waste disposal | Throughout the | Each Week | FEP-01/558/2018/A | ✓ |
| points are provided. Wastes are collected and removed from site in a timely manner. General refuse is collected on a regular basis. | works | | FEP-02/558/2018/A FEP-03/558/2018/B | ✓ ✓ |
| Waste storage areas are | Throughout the | Each Week | FEP-01/558/2018/A | ✓ |
| properly cleaned and do not cause windblown litter and dust nuisance. Appropriate measures to reduce windblown litter and dust nuisance of waste will be adopted, e.g. by either covering trucks or by transporting wastes in enclosed containers. | works | | FEP-02/558/2018/A FEP-03/558/2018/B | ✓ ✓ |
| | Thurst all the | Гоор \//!: | FED 04/F50/0040/A | |
| Different types of waste are segregated in different containers or skip to enhance reuse and recycling of material and proper disposal of waste. | Throughout the works | Each Week | FEP-01/558/2018/A FEP-02/558/2018/A FEP-03/558/2018/B | ✓ ✓ ✓ |

www.em.com Version: 0 Project No.: 0505354 Client: CAPCO, HK Electric, HKLTL 9 February 2023
P:\Projects\0505354 CLP Power Hong Kong Limited FSRU Pre-con EM&A.RC\02 Deliverables\28 Monthly EM&A Report\2023-01\Rev 0\0505354_Monthly EM&A

Report_2023-01_Rev_0.docx

HONG KONG OFFSHORE LNG TERMINAL PROJECT Monthly Environmental Monitoring and Audit (EM&A) Report for January 2023

| Activities | Timing | Checking Frequency | Works Area(s) | Compliance (✓) / |
|--|----------------------|-----------------------|-------------------|---|
| | | | | Non-compliance (x) |
| Chemical wastes are stored, handled and disposed of in accordance with the <i>Code of Practice</i> | Throughout the works | Each Week | FEP-01/558/2018/A | No chemical waste was produced in the reporting period. |
| on the Packaging, Labelling and Storage of Chemical Wastes, published by the EPD. | | | FEP-02/558/2018/A | No chemical waste was produced in the reporting period. |
| Chemical wastes are separated for special handling and appropriate treatment at the Chemical Waste Treatment Centre at Tsing Yi. | | | FEP-03/558/2018/B | No chemical waste was produced in the reporting period. |

Project No.: 0505354 Client: CAPCO, HK Electric, HKLTL 9 February 2023 www.em.com Version: 0